

1995 Land Rover Range Rover County LWB



SALHF1347SA654716



Vehicle History Report™

**1995 LAND ROVER
RANGE ROVER
COUNTY LWB**

VIN: SALHF1347SA654716
4 DOOR WAGON/SPORT
UTILITY
4.2L V8 F
GASOLINE
ALL WHEEL DRIVE



No accidents or damage reported to CARFAX



36 Service history records



3 Previous owners



Types of owners: Personal lease, Personal



Last owned in California



162,592 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/26/24 at 4:29:28 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired



Title History

	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem	No Problem	No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	No Problem	No Problem	No Problem



Ownership History

The number of owners is estimated

	Owner 1	Owner 2	Owner 3
Year purchased	1995	1999	2019
Type of owner	Personal lease	Personal	Personal
Estimated length of ownership	3 yrs. 11 mo.	20 years	5 yrs. 9 mo.
Owned in the following states/provinces	California	California	California
Estimated miles driven per year	11,023/yr	3,994/yr	1,253/yr
Last reported odometer reading	44,126	155,897	162,592



Detailed History



Owner 1
Purchased:
1995



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Lease
Vehicle
11,023 mi/yr

Date	Mileage	Source	Comments
01/31/1995		California Motor Vehicle Dept.	Title issued or updated - First owner reported - Titled or registered as personal lease vehicle
09/15/1995	11,280	California Inspection Station Yorba Linda, CA	Passed emissions inspection
10/25/1995		California Motor Vehicle Dept.	Title issued or updated - Loan or lien reported - Owner purchased from leasing company

01/26/1998 30,658 California
Inspection Station
Palmdale, CA **Passed emissions inspection**





01/15/1999 44,126 California
Inspection Station
Corona del Mar, CA **Passed emissions inspection**

 **Owner 2**
Purchased:
1999



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
3,994 mi/yr

Date	Mileage	Source	Comments
01/15/1999		California Motor Vehicle Dept.	Title issued or updated - New owner reported
12/18/1999		California Motor Vehicle Dept. Studio City, CA	Title issued or updated
01/29/2001	84,080	California Inspection Station	Passed emissions inspection
03/07/2001		Land Rover South Bay Redondo Beach, CA 310-975-6999 ★ 4.2 / 5.0 126 Verified Reviews ❤️ 71 Customer Favorites	 Vehicle serviced
06/08/2001		Land Rover South Bay Redondo Beach, CA 310-975-6999 ★ 4.2 / 5.0 126 Verified Reviews ❤️ 71 Customer Favorites	 Vehicle serviced
08/01/2001		Land Rover South Bay Redondo Beach, CA 310-975-6999 ★ 4.2 / 5.0 126 Verified Reviews ❤️ 71 Customer Favorites	 Vehicle serviced
08/28/2001		Land Rover South Bay Redondo Beach, CA 310-975-6999	 Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

09/13/2001

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

11/03/2001

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

11/30/2001

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

05/01/2002

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

07/10/2002

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

10/08/2002

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0
126 Verified Reviews
❤️ 71 Customer Favorites

10/19/2002

Land Rover South Bay
Redondo Beach, CA



Vehicle serviced

310-975-6999

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

11/11/2002

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

01/09/2003 116,014

California
Inspection Station

Passed emissions inspection

01/25/2003

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

03/10/2003

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

04/08/2003

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

07/07/2003

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

09/17/2003

Land Rover South Bay
Redondo Beach, CA
310-975-6999






















Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

 71 Customer Favorites

10/08/2003		Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced
10/27/2004		Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced - Oil and filter changed - Steering/suspension checked - Rear brake pads replaced
09/26/2006		Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced - Trim checked - Fuel tank replaced - Cooling system checked
09/26/2006	128,697	California Inspection Station	Passed emissions inspection
10/09/2006		Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced
11/29/2006		Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced - Recommended maintenance performed - Cooling system checked - Cylinder head gasket(s) replaced
01/30/2007	128,891	Land Rover South Bay Redondo Beach, CA 310-975-6999  4.2 / 5.0 126 Verified Reviews  71 Customer Favorites	 Vehicle serviced
04/09/2007	133,587	Land Rover South Bay Redondo Beach, CA	 Vehicle serviced Maintenance inspection completed

Redondo Beach, CA
310-975-6999

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

- ▼ Maintenance inspection completed
- Wiper(s) replaced
- Oil and filter changed
- Brakes checked

06/04/2007 136,083

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

07/12/2007

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

- Maintenance inspection completed
- Cooling system checked
- Brakes checked

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

08/02/2007 136,307

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

- Recommended maintenance performed
- Alternator replaced
- Battery replaced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

10/12/2007 140,112

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

- Maintenance inspection completed
- Alternator replaced
- Battery/charging system checked
- Cooling system checked
- Drivability/performance checked
- Antifreeze/coolant flushed/changed

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

01/12/2008 144,846

California
Inspection Station

Failed emissions inspection

01/30/2008 145,650

California
Inspection Station

Passed emissions inspection

07/31/2008 151,466

Land Rover South Bay
Redondo Beach, CA
310-975-6999



Vehicle serviced

- Maintenance inspection completed
- Alternator replaced

★ 4.2 / 5.0

126 Verified Reviews

♥ 71 Customer Favorites

06/09/2012

California

Registration updated when owner

Motor Vehicle Dept.
Porter Ranch, CA

moved the vehicle to a new location

07/10/2012 152,236 California
Inspection Station
Northridge, CA

Failed emissions inspection

01/18/2019 155,897 California
Inspection Station
San Diego, CA

Passed emissions inspection

 **Owner 3**
Purchased:
2019




Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
1,253 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------

01/19/2019	155,924	California Motor Vehicle Dept. Los Gatos, CA	Odometer reading reported
------------	---------	--	----------------------------------

01/22/2019		California Motor Vehicle Dept. Los Gatos, CA	Title issued or updated - New owner reported
------------	--	--	--

11/23/2020	157,334	Exclusive British European Campbell, CA 408-374-0131	 Vehicle serviced - Oil and filter changed - Fluids checked
------------	---------	---	---



★ 4.7 / 5.0

12 Verified Reviews

♥ 19 Customer Favorites


01/13/2021	157,342	Fast Smog Campbell, CA 408-608-8788	 Vehicle serviced - Emissions inspection performed
------------	---------	---	---



★ 4.6 / 5.0

9 Verified Reviews

01/13/2021		California Inspection Station Campbell, CA	Passed emissions inspection
------------	--	--	------------------------------------

03/17/2021	157,498	Exclusive British European Campbell, CA 408-374-0131	 Vehicle serviced
------------	---------	---	---



★ 4.7 / 5.0

12 Verified Reviews

♥ 19 Customer Favorites

05/20/2022 157,990 Exclusive British European
Campbell, CA
408-374-0131
★ 4.7 / 5.0
12 Verified Reviews
♥ 19 Customer Favorites



- Vehicle serviced**
- Electrical system checked
 - License plate light bulb(s) replaced
 - Rear brake pads replaced
 - Tires rotated

01/09/2023 159,349 Exclusive British European
Campbell, CA
408-374-0131
★ 4.7 / 5.0
12 Verified Reviews
♥ 19 Customer Favorites



- Vehicle serviced**
- Tires rotated
 - Oil and filter changed

01/11/2023
California
Inspection Station
Campbell, CA

Passed emissions inspection

08/07/2023 161,474 Exclusive British European
Campbell, CA
408-374-0131
★ 4.7 / 5.0
12 Verified Reviews
♥ 19 Customer Favorites



- Vehicle serviced**
- Power steering hose(s)/line(s) replaced
 - Serpentine belt replaced
 - Drive belt(s) replaced
 - Engine checked
 - Transmission mount(s) replaced
 - Engine replaced
 - Fuel filter replaced
 - Oil pan gasket replaced
 - Transmission cooler line(s) repaired/replaced
 - Water pump replaced
 - Spark plug wires replaced
 - Ignition system checked
 - Spark plug(s) replaced
 - Air filter replaced
 - Oil and filter changed
 - Antifreeze/coolant flushed/changed

05/13/2024 162,592 Exclusive British European
Campbell, CA
408-374-0131
★ 4.7 / 5.0
12 Verified Reviews
♥ 19 Customer Favorites



- Vehicle serviced**
- Airbag system checked
 - Tires rotated
 - Oil and filter changed

Have Questions? Please visit our Help Center at www.carfax.com.



Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
10/26/24 4:29:28 PM (CDT)

7 TO 7 AUTO REPAIR

7955 Arjons Drive
 San Diego, CA. 92126
 Phone: 858-549-0272 Fax: 858-549-0760
 Email: 7to7auto@live.com

INVOICE

14739

Org. Est. # 004526
 BAR# ARD00287161
 EPA# CAL000428227

Invoice from History

Work Completed : 07/14/2017 Date: 02/06/2019

BRITISH MOTORS 1995 Land Rover - Range Rover County LWB - 4.2L, V8 (261CI)
 7955 ARJONS DRIVE #A Lic # : 3BLM614 Odometer In : 155759
 San Diego, CA 92126
 Home 858-71 -- Office 30 VIN # : SALHF1347 SA654716

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
MUD FLAPS MXC5587	4.00	9.50	38.00	Install mud flaps Install mud flaps	70.00
Suspension Bellows - Rear A2229	1.00	110.00	110.00	Need airsprings Remove and replace all four suspension bellows	175.00
Hose Coupler - M-M 3/8" 28602	1.00	2.50	2.50	Remove and replace all four suspension bellows Customer supplied both front and one rear bellows	
BRAKE FLUID DOT4	2.00	5.00	10.00	REPLACE FRONT DISC PADS	70.00
BRAKE & PART CLEANER B&PC	2.00	4.00	8.00	REPLACE FRONT BRAKE PAD LININGS. CHECK FRONT BRAKE DISC ROTOR CONDITION. CLEAN AND LUBRICATE BRAKE CALIPERS AND SLIDE MECHANISMS. BLEED AIR FROM SYSTEM. ROAD TEST VEHICLE.	
BRAKE PAD SET - Front SFP500180	1.00	37.00	37.00	REPLACE REAR DISC PADS	70.00
BRAKE PAD SET - Rear SFP500200	1.00	38.50	38.50	REPLACE REAR BRAKE PAD LININGS. CHECK REAR BRAKE DISC ROTOR CONDITION. CLEAN AND LUBRICATE BRAKE CALIPERS AND SLIDE MECHANISMS. BLEED AIR FROM SYSTEM. ROAD TEST VEHICLE.	
				BATTERY - Remove & Replace - All Applicable Models - [Includes: Test.] Remove & replace customer supplied battery	35.00
				ALTERNATOR ASSEMBLY - Remove & Replace - All Applicable Models Remove alternator from customer's engine & replace alternator on vehicle	77.00

Org. Estimate 131.56 Revisions 516.60 Current Estimate 648.16

Revision # 1, Previous Estimate Amount: 131.56, Additional Cost: 240.75, Revised Estimate: 372.31, Parts: \$93.50 Labor: \$140.00 Sublet: \$0.00
 Taxes & Fees: \$7.25 Authorized by - Dara, Date - 7/6/2017, Time - 2:56 PM, Initiated By - Shop, Written By - Coates, Paul, Reason - F&R Brake Pads,
 Phone Number - Cellular: 858-733-1030

Revision # 2, Previous Estimate Amount: 372.31, Additional Cost: 275.85, Revised Estimate: 648.16, Parts: \$95.45 Labor: \$175.00 Sublet: \$0.00
 Taxes & Fees: \$5.40 Authorized by - Dara, Date - 7/6/2017, Time - 2:56 PM, Initiated By - Shop, Written By - Coates, Paul, Reason - F&R Brake Pads,
 Phone Number - Cellular: 858-733-1030

Labor:	497.00
Parts:	244.00
SubTotal:	741.00
Tax:	18.91
Total:	759.91
Bal Due:	\$0.00

[Payments - Check - \$759.91]

Thank You For Your Business

Vehicle Received: 6/19/2017

Customer Number : 574

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

7 TO 7 AUTO REPAIR

7955 Arjons Drive
 San Diego, CA. 92126
 Phone: 858-549-0272 Fax: 858-549-0760
 Email: 7to7auto@live.com

INVOICE

16591

Org. Est. # 006607
 BAR# ARD00287161
 EPA# CAL000428227

Invoice from History

Work Completed : 01/19/2019 Date: 02/06/2019

BRITISH MOTORS

7955 ARJONS DRIVE #A
 San Diego, CA 92126
 Home 8: 30 -- Office 8:

1995 Land Rover - Range Rover County LWB - 4.2L, V8 (261CI)
 Lic # : 3BLM614 Odometer In : 155897

VIN # : SALHF1347 SA654716

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
3/4" Vacuum Hose Hose	2.50	5.00	12.50	CUSTOMER CONCERN: Cruise control vacuum lines are cracked, steering wheel is off center, ABS light is on, verify vehicle will pass smog FOUND: Replaced vacuum lines, centered steering wheel, unable to duplicate ABS light (light is not on) when vehicle arrived but came on after smog. Removed and cleaned all four ABS sensors and light went off. There are leaks in the evap emissions system. Gas tank needs to be dropped to for a thorough examination. FUEL TANK - Remove & Replace - All Applicable Models Repaired evap emissions system leaks on 3/4" hose and fuel pump fittings Smog BAR-97 Smog Hazardous Materials	204.00
3/16" Vacuum Hose Hose	3.00	1.18	3.54		221.00
					65.00
					7.59

Org. Estimate 106.50 Revisions 289.34 Current Estimate 395.84

Revision # 1, Previous Estimate Amount: 106.50, Additional Cost: 289.34, Revised Estimate: 395.84, Parts: \$16.04 Labor: \$267.80 Sublet: \$0.00
 Taxes & Fees: \$5.50 Authorized by - Dara, Date - 1/18/2019, Time - 2:24 PM, Initiated By - Shop, Written By - Coates, Paul, Reason - Evap leaks,
 Phone Number - Home: 858-733-1030

Labor:	425.00
Parts:	16.04
Sublet:	65.00
HazMat:	7.59
SubTotal:	513.63
Tax:	1.24
Total:	514.87
Bal Due:	\$0.00

[Payments - Visa - Debit - \$514.87]

Thank You For Your Business

Vehicle Received: 1/18/2019

Customer Number : 574

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.7to7autorepair.com

Our Email Address: 7to7auto@live.com



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 01/18/2019@13:18:41

Model Year:	1995	Make:	LAND ROVER	Model:	RANGE ROVER COUNTY LWB
License:	3LBM614	State:	CA	VIN:	SALHF1347SA654716
Engine Size:	4.20 L	Type:	Truck	Transmission:	Automatic
GVWR:	6019	Test Weight:	N/A	Cylinders:	8
Odometer:	155,897	Certification:	California	VLT Record #:	26573
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: HZ553416

DMV ID Number: 1806Z677H136

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB08	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	901	15.3	0.0	100	26	7	1.00	0.00	0.00	Pass
2500 RPM	2538	15.2	0.0	180	11	8	1.10	0.10	0.00	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

SMOG TEST ONLY

8242-A MIRAMAR ROAD, SAN DIEGO, CA 92126

858-695-9053

Station Number: TC114669

Technician Name/Number:

TRAN, THIEN/EO122688

Repair Tech Name/Number:

Software Version/EIS Number:

1805 / EP727603

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date: 1/18/19

Technician's Signature



Congleton Service, Inc.
354 Prim Rd. Suite 3
Colchester, VT 05446 US
(802) 578-2461
info@congletonservice.com

Packing Slip

BILL TO

Los Gatos, CA 95032 USA

INVOICE # 1151110
DATE 01/30/2019

DATE	ACTIVITY
01/30/2019	RRC Wiper Cap Congleton Service Parts, 5
01/30/2019	Shipping and Handling Shipping & Handling, 1

Labor and towing will not be covered from other shops. It is the customers responsibility and cost to return a vehicle to Congleton Service for any warranty service. There will be no warranties based on a diagnosis from another repair facility. By signing or paying this invoice the customer agrees that all charges are approved & waives all rights to credit card chargebacks & or stopped checks.

Safari HP Inc
3454 Aloma Ave
Winter Park, FL 32792
4075174983
info@safarihp.com
www.safarihp.com



Invoice

BILL TO

Los Gatos, CA 95032

SHIP TO

Los Gatos, CA 95032

INVOICE # 6980

DATE 03/11/2019

TERMS 100 Days

CUSTOMER TYPE

Parts

SALES REP.

Joe

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
BTR9926LNFAI	BTR9926LNFAI Illumination Assembly Selector Indicator (Pair) EBAY PURCHASE	2	6.495	12.99

PAID

PAYMENT 12.99
BALANCE DUE **\$0.00**



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE
 Invoice Number
 1262294
 Customer Number
 525038

Bill to:

LOS GATOS, CA 95032
 Phone

Ship to:

LOS GATOS, CA 95032

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS		
04/08/19 07:48 PM		GTRAC		SIMI VALLEY,		Cyber Order 5045290		
PHONE NUMBER			ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
972/672-5727			04/08/2019		Eric Riston - Ext 231		1385320	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION			UNIT PRICE	AMOUNT
8	8	0	NTC7867	BUMPER END CLIPS 4 PER BUMPER END			1.09	8.72
1	1	0	NTC1950	BRACKET REAR END CAP/BUMPER RIGHT			7.95	7.95
1	1	0	NTC5232G	BUMPER END CAP REAR RIGHT			71.95	71.95
1	1	0	NTC5233G	BUMPER END CAP REAR LEFT			71.95	71.95

Shipping Charges	13.33
NonTaxable Subtotal	0.00
Taxable Subtotal	173.90
Tax (7.25%)	12.62
Total	186.52
Less Payments/Credits	186.52
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169

FAX: 518-664-6641

RoverParts.com • MiniCarParts.net • RoverParts.com • MiniCarParts.net



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1281779

Customer Number
525038

Bill to:

Ship to:

LOS GATOS, CA 95032
Phone

1;
LOS GATOS, CA 95032

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS	
07/15/19 02:19 PM		1CLML		SIMI VALLEY,		Cyber Order 5053524	
PHONE NUMBER		ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
972/672-5727		07/15/2019		Brian Westervelt - Ext 238		1406234	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION		UNIT PRICE	AMOUNT
1	1	0	PRC7045G	WASHER PUMP WINDSHIELD FROM 89 KIT		34.95	34.95
1	1	0	AMR3849	LINK LEAD WASHER PUMP		0.00	0.00
1	1	0	STC1454	WINDSHIELD WASHER PUMP - SEE PRC704		0.00	0.00

Shipping Charges	3.95
NonTaxable Subtotal	0.00
Taxable Subtotal	38.90
Tax (7.25%)	2.82
Total	41.72
Less Payments/Credits	41.72
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169 FAX: 518-664-6641
RoverParts.com • MiniCarParts.net • ClearviewMirrorsUSA.com



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1289915

Customer Number
525038

Bill to:

Ship to:

LOS GATOS, CA 95032 1748 US

1
LOS GATOS, CA 95032

Phone

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS		
08/26/19 12:41 PM		FHD		CLIFTON PARK		Cyber Order 931437585026		
PHONE NUMBER			ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
972/672-5727			08/26/2019		Dave Furiani - Ext 233		1415064	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION			UNIT PRICE	AMOUNT
1	1	0	AMR3107A	ALTERNATOR 100 AMP			165.36	165.36
1	1	0	EFS	EBAY ****FREE****SHIPPING*****			0.00	0.00

THANK YOU FOR YOUR ORDER! ANY QUESTIONS PLEASE CALL 1-800-533-2210 EXT.233
 THANKS, DAVE.

NonTaxable Subtotal	0.00
Taxable Subtotal	165.36
Tax (7.25%)	11.99
Total	177.35

Thank You!

PHONE: 800-533-2210 or 518-664-6169 FAX: 518-664-6641
RoverParts.com • MiniCarParts.net • ClearviewMirrorsUSA.com

CRUTCHFIELD

1 Crutchfield Park
Charlottesville, Virginia 22911 -9097
www.crutchfield.com

Sold to

LOS GATOS, CA 950321748

Ship to

1,
LOS GATOS, CA 950321748

CID: 39076441

A message from Bill Crutchfield

Thank you for choosing Crutchfield. Please let us know how we can help you enjoy your new gear.

Because my name is on the business, I work hard to make sure you are thrilled with our service. I'm always eager to hear your suggestions. Feel free to send me a message at crutchfield.com/bill-listens.

Bill Crutchfield

Order number

46472245

Invoice number

27528006

Order date

9/15/2019

Date processed

9/15/2019

Shipping method

STANDARD

Your advisor

Web Order

Quantity ordered	Quantity backordered	Quantity shipped	Item number	Description	Unit price	Amount
1	0	1	867RCA6C5M	Wet Sounds WWX-RCA 6CH 17FT	44.99	44.99
1	0	1	120V12MANL	T-SPEC MANL Fuse Holder	19.99	19.99
			WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .			
1	0	1	120MANL100	T-SPEC MANL Fuses 100 Amp (2)	3.99	3.99
			WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .			
1	0	1	142BTUCD08	Universal Battery Terminal	39.99	39.99
1	0	1	575R14X2	Rockford Fosgate Prime R14X2	39.99	39.99
1	0	1	120RTN9	T-SPEC Ring Terminal	5.99	5.99
			WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .			
50	0	50	007CSW14	Crutchfield Speaker Wire 14 ga	0.59	29.50
			WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .			

Special messages

Below are some phone numbers to call if you need help. Please see the back of this invoice for information about our guarantee and how to return an item.

Need help?

Tech Support 1-800-955-9094
Customer Support 1-800-955-9091
¿Habla español? 1-800-955-9039



27528006-01

INVFRONT March 2012

Invoice summary

Merchandise Total: 247.23
Tax: 22.54
Order Total: 269.77

Payments:
MasterCard 269.77

CRUTCHFIELD

1 Crutchfield Park
Charlottesville, Virginia 22911 -9097
www.crutchfield.com

Sold to

LOS GATOS, CA 950321748

Ship to

LOS GATOS, CA 950321748

CID: 39076441

A message from Bill Crutchfield

Thank you for choosing Crutchfield. Please let us know how we can help you enjoy your new gear.

Because my name is on the business, I work hard to make sure you are thrilled with our service. I'm always eager to hear your suggestions. Feel free to send me a message at crutchfield.com/bill-listens.

Bill Crutchfield

Order number

46472245

Invoice number

27528006

Order date

9/15/2019

Date processed



9/15/2019

Shipping method

STANDARD

Your advisor

Web Order

Quantity ordered	Quantity backordered	Quantity shipped	Item number	Description	Unit price	Amount
19	0	19	007CPWR4	Crutchfield Power Wire Red	2.99	56.81
				WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .		
2	0	2	007CPWB4	Crutchfield Ground Wire Black	2.99	5.98
				WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov .		

Special messages

Below are some phone numbers to call if you need help. Please see the back of this invoice for information about our guarantee and how to return an item.

Need help?

Tech Support 1-800-955-9094
Customer Support 1-800-955-9091
¿Habla español? 1-800-955-9039



27528006-01

INVFRONT March 2012

Invoice summary

Merchandise Total: 247.23
Tax: 22.54
Order Total: 269.77

Payments:
MasterCard 269.77

Save this invoice (and the manufacturer's boxes)

This invoice is proof of purchase for warranty service. Please save the box and packing materials until your equipment is out of warranty.

Missing something?

Please thoroughly check all of the package contents.

Parts may have shifted to the bottom of the box and could be lost in the packing "peanuts."

Need help installing or operating your products?

Call toll-free 1-800-955-9094, 7 days a week or visit crutchfield.com/techsupport.

Please use a phone near the equipment or vehicle.

Please have the following items with you:

- Your Owner's Manual (and MasterSheet™ car stereo installation instructions, if applicable)
- The make, model and year of your vehicle (if you're calling about car products)
- Any tools, cables, or accessories you might need
- If you think an item is defective, please call for troubleshooting help before returning it.

Or try our online technical support FAQ

- Find answers to common troubleshooting questions at crutchfield.com/techsupport.

60-day returns

We want you to enjoy the items you purchase from Crutchfield. If you are not satisfied with your purchase, you may return items that are complete and like new for any reason within 60 days.

Refund options You may choose an exchange or a refund for the full amount of the items you purchased.

Refund method Refunds must be issued to the same credit card, debit card, gift certificate, or other form of payment used in the original transaction.

Non-refundable The money-back guarantee does not apply to prepaid installations, or navigation map upgrades once the installation or map upgrade has been performed.

Items must be new Crutchfield may refuse a customer return or charge a restocking fee when the returned item is not like new. Examples of conditions that will lead to refused returns or restocking fees include when the returned item has:

- A different serial number than the one Crutchfield originally shipped.
- Missing parts or the original product packing material.
- Damage because it was improperly packaged for return shipment.
- Been heavily used (such as when a camera shutter counter shows that more than 300 pictures have been taken).
- Damage from drops, spilled liquid, or mishandling (including in-flight or other damage to drones)

For return authorization, call 1-800-955-9091 or use our online return request form

Return shipping using a convenient UPS ARS tag is only \$10 on most items (exceptions include large items requiring special delivery). The \$10 return shipping cost will be deducted from your merchandise credit or refund. Visit Crutchfield.com/returns for more information.


Other contact information

- ¿Habla Español? 1-800-955-9039 (Spanish only).
- TDD (Telephone Device for the Deaf) 1-800-388-9753
- Administrative Offices: 1-434-817-1000 (not toll-free) 8 am to 5 pm Eastern time, Monday-Friday.
- Check on an item you haven't received yet by visiting crutchfield.com/orderstatus. Or, call 1-800-955-9091, 7 days a week.

We make our own earth-friendly packing peanuts

Made from starch in our own distribution center, our non-static peanuts are 100% biodegradable. You can save them and re-use them, or safely dispose of them by dissolving them. Simply put them in a sink and run a little water over them.

Or, better yet, put them in your compost pile.



Charles, one of our Technical Support Specialists, can help you with big installation projects and small system tweaks.

CRUTCHFIELD®

INVBACKBW_2018-12.

CRUTCHFIELD

1 Crutchfield Park
 Charlottesville, Virginia 22911 -9097
 www.crutchfield.com

Sold to
 LOS GATOS, CA 950321748

Ship to
 1
 LOS GATOS, CA 950321748

CID: 39076441

A message from Bill Crutchfield


Thank you for choosing Crutchfield. Please let us know how we can help you enjoy your new gear.

Because my name is on the business, I work hard to make sure you are thrilled with our service. I'm always eager to hear your suggestions. Feel free to send me a message at crutchfield.com/bill-listens.

Bill Crutchfield

Order number
46511058


Invoice number	Order date	Date processed	Shipping method	Your advisor
27561683	9/29/2019	9/30/2019	STANDARD	Web Order

Quantity ordered	Quantity backordered	Quantity shipped	Item number	Description	Unit price	Amount
1	0	1	15410007	Dynamat 10007 Roller	19.99	19.99
1	0	1	15410435	Dynamat 10435 Xtreme	99.99	99.99
1	0	1	091165AS3	Focal Access 165AS3	479.00	479.00
20	0	20	007CSW14	Crutchfield Speaker Wire 14 ga	0.59	11.80
 WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov.						

Special messages

Below are some phone numbers to call if you need help. Please see the back of this invoice for information about our guarantee and how to return an item.

Need help?
 Tech Support 1-800-955-9094
 Customer Support 1-800-955-9091
 ¿Habla español? 1-800-955-9039



27561683-01

INVFRONT March 2012

Invoice summary

Merchandise Total:	610.78
Tax:	55.72
Order Total:	666.50
Payments:	
Gift Card	11.00
MasterCard	655.50

Your Account

Saved payment [x Delete](#)

x-
 Expires: 11/2020

Selected Vehicle [Edit](#)

1993 Land Rover County Sport Utility

[Shop by vehicle](#)

Rewards [+ More](#)

242 available 0 pending \$0 balance

You only need 8 more points to earn your next Reward Card



[Change password](#)

[Orders](#)

Order date: 12/19/2017


Bill to: LOS GATOS, CA 95032
 Ship to: LOS GATOS, CA 95032
 Order total: \$237.73

Order #: 44489954

Invoice #: 25750318

Status: Shipped

UPS 3 Day Select®: 3D UPS / Tracking #1Z2807701299550504



Audiofrog GS42 4" 2-Way Speakers

Item #898GS42

★ [Rate and review this product](#)

📄 [Download owner's manual](#)

Associated vehicle: 1993 Land Rover County

Speaker location: Rear Pillar

Quantity	Price	Total
1	\$229.99	\$229.99




Crutchfield Speaker Wire 10 ga per foot

Item #007CSW10

★ [Rate and review this product](#)

Quantity	Price	Total
6	\$1.29	\$7.74



Metra IBCFSQ10PK Female Quick Slide Terminals
 0.250/0.205/0.187/0.110

Item #120FQS10PK

★ [Rate and review this product](#)

Quantity	Price	Total
1	\$0.00	\$0.00

Subtotal	\$237.73
Shipping	Free
Total	\$237.73

✓ Paid by Mastercard
 \$201.73

 Request a return

 Print

 Customer Support: 1.800.955.9091

 Tech Support: 1.800.955.9094

Order date: 11/30/2017

Order #: 44394388

Bill to: LOS GATOS, CA 95032
Ship to: LOS GATOS, CA 95032
Order total: \$1644.89

Invoice #: 25659860

Status: Shipped

UPS 3 Day Select®: 3D UPS / Tracking #1ZV4V6421232916383

UPS 3 Day Select®: 3D UPS / Tracking #1Z2807701298962722




Rockford Fosgate T1S-1x10 Single 10" Sealed Loaded Enclosure

Item #575T1S110

Quantity	Price	Total
1	\$549.99	\$549.99

★ Rate and review this product

■ Download owner's manual




Rockford Fosgate Power T252-S 5-1/4" Component System

Item #575T252S

Quantity	Price	Total
1	\$249.99	\$249.99

★ Rate and review this product

■ Download owner's manual



Rockford Fosgate RFK4X Amplifier Wiring Kit 4 gauge Power

Item #575RFK4X

Quantity	Price	Total
1	\$109.99	\$109.99

★ Rate and review this product

■ Download owner's manual



Wet Sounds WW-RCA-6CH 5M 6-Channel RCA 5 Meters

Item #867RCA6C5M

Quantity	Price	Total
1	\$84.99	\$84.99

★ Rate and review this product

■ Download owner's manual



Bojo ATH-CR6L-NGL 6pc. Plastic Pry Tool Kit w/Lrg Pry Tool

Item #126CR6LNGL

Quantity	Price	Total
1	\$19.99	\$19.99

★ Rate and review this product



Pro.Fit DM 45-33 Wire Worm Tool - 48" long by 3/8" width

Item #042DM4533

Quantity	Price	Total
1	\$9.99	\$9.99

★ Rate and review this product



Metra ethereal IBR-CTM34 Adhes 3/4" x 3/4" Pkg of 100

Item #120CTM34

Quantity	Price	Total
1	\$8.99	\$8.99

★ Rate and review this product



Install Bay IBR42 Flex Loom Tubing 1/2"

Item #120IBR42

Quantity	Price	Total
2	\$3.99	\$7.98

★ Rate and review this product



Install Bay IBR33 Assorted Cable Ties 4"/6"/8" - 24 total

Item #120IBR33

★ Rate and review this product

Quantity	Price	Total
1	\$2.99	\$2.99



Rockford Fosgate Program Extended Amplifier Warranty

Item #000575EWP

Quantity	Price	Total
0	\$0.00	\$0.00



Rockford Fosgate T1000X5AD Power 100W x 4 + 600W x 1 Car Amplifier

Item #575T1000X5

★ Rate and review this product

📄 Download owner's manual

Quantity	Price	Total
0	\$599.99	\$0.00

Subtotal \$1044.90

Shipping Free

Total \$1044.90

✓ Paid by Mastercard
\$1044.90

Invoice #: 25677633

Status: Shipped

UPS 3 Day Select®: 3D UPS / Tracking #1Z2807701299077679



Rockford Fosgate T1000X5AD Power 100W x 4 + 600W x 1 Car Amplifier

Item #575T1000X5

★ Rate and review this product

📄 Download owner's manual

Quantity	Price	Total
1	\$599.99	\$599.99



Rockford Fosgate Program Extended Amplifier Warranty

Item #000575EWP

Quantity	Price	Total
2	\$0.00	\$0.00

Subtotal \$599.99

Shipping Free

Total \$599.99

✓ Paid by Mastercard
\$599.99



Request a return



Print

CERTIFICATE OF PERFORMANCE VERIFICATION



Model #: **T1000X5AD** Serial #: **0001131341-48** Birth Date: **11/06/2017** Test System: **RF-RATS-4**

SYSTEM OPERATION	Idle Current Measure Current Draw at Idle					System Voltage Check System Reference Voltages								
	A PASS					V1	5.006	V2	N/A					
	Bias Set Output Channel Bias					High Rail Voltage Check Amplifier Rail Voltages								
	CH1	N/A	CH2	N/A	CH3	N/A	CH4	N/A	V1	N/A	V2	N/A	V3	N/A
	DC Offset Check for No DC Voltage on Outputs					Low Rail Voltage Check Amplifier Rail Voltages								
CH1	-.003	CH2	-.001	CH3	-.000	CH4	-.003	CH5	.020	V1	10.64	V2	-10.20	
Dark Current Current Draw < 100uA					Gain Tracking Check Gain Tracking Between Channels (dB)									
A PASS					CH1	0.294	CH2	0.294	CH3	0.327	CH4	0.327		

SIGNAL	Frequency Response 20Hz-20kHz Sweep @ 1W RMS					High Pass Crossover Check 20Hz-20kHz Sweep @ 1W RMS														
	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	N/A
	Remote Level & 2/4/5 Ch. Select Check 20Hz-20kHz Sweep @ 1W RMS					Low Pass Crossover & Punch EQ Check 20Hz-20kHz Sweep @ 1W RMS														
	CH1	N/A	CH2	N/A	CH3	N/A	CH4	N/A	CH5	PASS	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS
	Common Mode Rejection Rated 20Hz-20kHz Sweep @ 1W RMS					Channel Separation from Left to Right 20Hz-20kHz Sweep @ Rated RMS Power														
	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	N/A
Signal to Noise Ratio 20Hz-20kHz Sweep @ Rated RMS Power					Total Harmonic Distortion 20Hz-20kHz Sweep @ 1W RMS (%)															
CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS	CH1	0.073	CH2	0.162	CH3	0.248	CH4	0.281	CH5	0.138	
Input Sensitivity Check Sensitivity @ Minimum					Total Harmonic Distortion Rated (%) 20Hz-20kHz Sweep @ Rated RMS Power															
CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS	CH1	0.251	CH2	0.249	CH3	0.248	CH4	0.254	CH5	0.303	

RELIABILITY	Short Protect Short All Channels Sequentially @ 1% THD					Thermal Test Thermistor Voltage Check														
	CH1	PASS	CH2	PASS	CH3	PASS	CH4	PASS	CH5	PASS	TH1	0.555	TH2	0.612	TH3	0.586	TH4	0.652	TH5	N/A
	Burn-In Amplifier Accelerated Life Monitor (45 sec. @ 1% THD)																			
CH	PASS	TH	PASS	V	PASS	BIAS	N/A	IR	PASS											

POWER	Channel Power Individual Channel Power @ 1% THD					Total Power Total RMS Power @ 1% THD					
	CH1	119	CH2	119	CH3	117	CH4	117	CH5	713	<h1 style="font-size: 2em;">1184 watts</h1>
	Total Power Total RMS Power @ Each Impedance @ 1% THD										
4Ω	1033	2Ω	1127	1Ω	713	2/1Ω	1184				

ALL Rockford Fosgate amplifiers are designed, developed, manufactured and tested in accordance with the CEA-2006 amplifier rating requirements. All tests conducted at 14.4Vdc, Min. Impedance, 1kHz(ab/ad) or 100Hz (bd) unless otherwise stated.
 ©2013 Rockford Corporation. All Rights Reserved. ROCKFORD FOSGATE, and associated logos where applicable are registered trademarks of Rockford Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners. Specifications subject to change without notice.



since 1979
autohausAZ
 Your Online Warehouse Source for Discount Auto Parts
 4100 S 38th St STE 150 | Phoenix, 85040
 Sales (800) 240-4620 | Fax (602) 276-6716
 www.AutohausAZ.com

Shipping Info:
 Richard Baker
 17329 Clearview Dr
 Los Gatos, CA 95032
 United States of America

Customer Info:
 Member 9112832
 baker6894@gmail.com
 972-672-5727

Order Number	Order Placed	Order Shipped
1688869	09/07/2019 09:40 AM	09/10/2019
Invoice	Shipped Via	Payment
1865393	USPS Priority Mail	PayPal

Comments					
Qty	Part Number	Description	List Price	Your Price	Total
1	003 820 28 10	Genuine Mercedes Seat Switch; Front Right with Memory	\$85.00	\$81.60	\$81.60

Parts Total - Including Core Deposits	\$81.60
Sales Tax	\$0.00
Shipping/Handling Charges	\$0.00
Invoice Total	\$81.60

Thank You For Your Order - Have a Really Great Day!

AutohausAZ strives to be both customer and environment friendly.
 We make every effort to use recyclable packing materials whenever possible.

Packed By: _____

Checked By: _____

Please carefully verify the accuracy of your ordered parts immediately upon receipt and prior to installation.



Rovers North, Inc.
 1319 VT Route 128
 Westford, Vermont
 05494-9601 USA
 ph 800 403-7591
 fx 802 879-9152

WEB INVOICES	
Sales Order # SO-988417	9/16/2019



North America's Source for Land Rover Parts at the Best Prices.

Customer	Ship To
LOS GATOS CA 95032 UNITED STATES	LOS GATOS CA 95032 UNITED STATES Tel: _____

Account	Sales Invoice	Terms	PO #	Account Rep	Ship VIA
57225	SI-1081453	CREDIT CARD		Erik Brennen	USPS First Class

Item	Coded	Description	Ord	Shp	B/O	Price	Net	Total
BTR5381RUN	BTR5381RUN	COVER PANEL LH SEAT R/R CLC	2	2		3.70	3.70	7.40
SH	SH	SHIPPING/HANDLING	1	1		0.00	4.34	4.34

Shipment Tracking Details		
Shipment Date	Delivery Method	Tracking Number
09/19/2019	USPS First Class	9400109898642368824421

Thanks for your order!	Tax Details EXEMPT \$0.000	Sub-Total	\$11.74
	Payment Details	Sales Tax	\$0.00
		Total	\$11.74
	PAID		Paid
Balance			\$11.74

#1037

September 7, 2019 at 9:15 pm from Online Store Unfulfilled

will ship 9/16



Range Rover Classic Front Inner Door Latch Driver Side \$95.00 x 1 \$95.00

Customer

Richard Baker
2 orders

CONTACT INFORMATION

baker6894@gmail.com

SHIPPING ADDRESS

Richard Baker
17329 Clearview Dr
Los Gatos CA 95032
United States

BILLING ADDRESS

Same as shipping address



1995 Range Rover Classic Speaker Cover Frames Passenger Side \$249.99 x 1 \$249.99



1995 Range Rover Classic Speaker Cover Frames Driver's Side \$249.99 x 1 \$249.99



Hella Fog Light Set \$140.95 x 1 \$140.95

Subtotal	4 items		
Shipping	Priority Mail (8.0 lb)		\$735.93
Tax			\$8.25
Total			\$744.18

Paid by customer \$744.18

YESTERDAY

\$724.53 USD was added to your Sep 10, 2019 payout. 9:40 pm

SEPTEMBER 7

Order confirmation email was sent to Richard Baker (baker6894@gmail.com). 9:15 pm

A \$744.18 USD payment was processed on the Mastercard ending in 9685. 9:15 pm

\$724.53 USD will be added to your Sep 10, 2019 payout. 9:15 pm

Richard Baker placed this order on Online Store (checkout #8520846442592). 9:15 pm

#1038

September 7, 2019 at 9:27 pm from Online Store Unfulfilled



Trim Clip Kit for 1995 Range Rover Classic Speaker Cover \$7.49 x 2 \$14.98

Customer

Richard Baker
2 orders

CONTACT INFORMATION

baker6894@gmail.com

SHIPPING ADDRESS

Richard Baker
17329 Clearview Dr
Los Gatos CA 95032
United States

BILLING ADDRESS

Same as shipping address

Subtotal	2 items		\$14.98
Shipping	First Class Package (0.2 lb)		\$3.09
Tax			\$0.00
Total			\$18.07
Paid by customer			\$18.07

YESTERDAY

\$17.30 USD was added to your Sep 10, 2019 payout. 9:40 pm

SEPTEMBER 7

Order confirmation email was sent to Richard Baker (baker6894@gmail.com). 9:28 pm

A \$18.07 USD payment was processed on the Mastercard ending in 9685. ▶ 9:27 pm

\$17.30 USD will be added to your Sep 10, 2019 payout. 9:27 pm

Richard Baker placed this order on Online Store (checkout #8520927871072). 9:27 pm

Your order has been shipped! - LRDirect by Global-e - order number
GE441797171GB

1 message

LRDirect <do-not-reply@global-e.com>
To: Richard Baker <baker6894@gmail.com>

Thu, Oct 31, 2019 at 10:07 AM



Parts and Accessories for
Land Rover® & Range Rover®
Vehicles - World-Wide Delivery

Dear [redacted]


Thanks for shopping at LRDirect. We just wanted to let you know that your order is on its way. Please note that if you paid for your order with a credit card, the transaction will appear on your bank statement under the name Global-e/re:LRDirect. Please note that your order cannot be changed.

Order Number:
GE441797171GB

Tracking Number:
5042310976

Order dispatched

Shipment Items

	DA6367 DA6367.C8	Qty 1	\$262.03
Shipping Method	Express Courier (Air)		
Payment Details	Paypal		
Subtotal			\$262.03
Shipping			\$27.35
Total			\$289.38



6 Enterprise Avenue
Clifton Park, New York 12065 USA

4109 Guardian Street
Simi Valley, California 93063 USA

INVOICE

Invoice Number
1318070

Customer Number
525038

Bill to:

Ship to:

LOS GATOS, CA 95032 US

LOS GATOS, CA 95032

Phone :

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE		SHIP VIA		F.O.B.		TERMS		
01/28/20 09:56 AM		FHD		CLIFTON PARK		Cyber Order 5068884		
PHONE NUMBER			ORDER DATE		SALES PERSON		OUR ORDER NUMBER	
972/672-5727			01/28/2020		Dave Furiani - Ext 233		1445183	
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION			UNIT PRICE	AMOUNT
1	1	0	ERR3340SKB	OIL FILTER KIT-INCLUDES PLUG AND WA			24.95	24.95
2	2	0	603659	OIL PAN DRAIN PLUG RR DISCO DEF			0.00	0.00
2	2	0	ERR3340	OIL FILTER SHORT			0.00	0.00
2	2	0	ETC7398	OIL PAN DRAIN PLUG WASHER			0.00	0.00

THANK YOU FOR YOUR ORDER! ANY QUESTIONS PLEASE CALL 1-800-533-2210 EXT.233
THANKS, DAVE.

Shipping Charges	14.35
NonTaxable Subtotal	0.00
Taxable Subtotal	39.30
Tax (7.25%)	2.85
Total	42.15
Less Payments/Credits	42.15
Balance Due	0.00

Thank You!

PHONE: 800-533-2210 or 518-664-6169 **FAX: 518-664-6641**
RoverParts.com • MiniCarParts.net • ClearviewMirrorsUSA.com



1319 VT ROUTE 128
WESTFORD, VT 05494

LAND ROVER PARTS AND
ACCESSORIES SINCE 1979

1 (800) 403-7591

WEB INVOICES

SO - 1007864

Mar-23-2020



Bill To	Ship To
LOS GATOS CA 95032 UNITED STATES Phone #	LOS GATOS CA 95032 UNITED STATES Phone

Account	SI	Terms	PO	Rep	Ship Via
57225	1099595	PayPal		Zack Griswold	USPS First Class

Item #	Bin Location	Description	Ord	Shp	B/O	Price	Net	Total
MWC2480	5-N-07-05	FINISHER TAILGATE HANDLE R/R CLC	2	2		\$17.70	\$17.70	\$35.40
MWC2707	BIN 1-8	BUSHING LOWER TAILGATE COVER PLATE R/R C	12	12		\$0.63	\$0.63	\$7.56
SH		SHIPPING/HANDLING	1	1		\$0.00	\$4.90	\$4.90

Shipment Date	Delivery Method	Shipment Tracking Number
Mar-17-2020	USPS First Class	9400109898642426829542

Tax Details		
EXEMPT \$0.000	Sub Total	\$47.86
	Sales Tax	\$0.00
Payment Details	Total	\$47.86
	Paid	\$0.00
	Balance	\$47.86

Rovers North - Land Rover Parts and Accessories Since 1979
1319 VT Rt 128
WESTFORD, VT, 05494
UNITED STATES
Tel : 8028790032

Order No.:
1007864

Date: March 22, 2020

: 57225

Your Billing Address

LOS GATOS CA95032
UNITED STATES

Your Shipping Address

LOS GATOS CA95032
UNITED STATES
Te

- 1 FINISHER TAILGATE HANDLE R/R CLC
- 2 BUSHING LOWER TAILGATE COVER PLATE R/R C
- 3 SHIPPING/HANDLING

Model #:	Ordered	Shipped			
MWC2480	2.00	0.00	\$17.70	\$0.00	\$35.40
MWC2707	12.00	0.00	\$0.63	\$0.00	\$7.56
SH	1.00	0.00	\$4.90	\$0.00	\$4.90

Your Payment Type : **PayPal**
Your Shipping Method : **USPS First Class**

SUMMARY TOTAL

Taxable	\$0.00
	\$47.86
	\$47.86
Tax:	\$0.00
Balance	\$47.86



6 Enterprise Avenue | 4109 Guardian Street
 Clifton Park, New York 12065 USA | Simi Valley, California 93063 USA

INVOICE

Invoice Number
1339938

Customer Number
525038

Bill to:

173
LOS GATOS, CA 95032 US

Phone

Ship to:

1
LOS GATOS, CA 95032

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper

All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE	SHIP VIA	F.O.B.	TERMS			
05/18/20 06:18 PM	FHD	SIMI VALLEY,	PPWEB			
PHONE NUMBER	ORDER DATE	SALES PERSON	OUR ORDER NUMBER			
972/672-5727	05/18/2020	Eric Riston - Ext 231	1468218			
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
1	1	0	6497B	STEERING DAMPER (BILSTEIN)	144.95	144.95
1	1	0	ANR3196G	TRAILER HITCH RECEPTACLE PLUG	12.49	12.49

Shipping Charges	13.65
NonTaxable Subtotal	0.00
Taxable Subtotal	171.09
Tax (7.25%)	12.41
Total	183.50

Thank You!

PHONE: 800-533-2210 or 518-664-6169 FAX: 518-664-6641
RoverParts.com • MiniCarParts.net • ClearviewMirrorsUSA.com



Your RoverParts.com Order Has Been Placed - Order No. RP-5080938


1 message

Atlantic British <orders@atlanticbritish.com>

Sat, May 30, 2020 at 1:52 PM

To: 

If you cannot see the images below, select "Show Images" in your browser or [Click Here](#) to view this message online.



Dear 

Thank you for shopping with Atlantic British Ltd.! We have received your order and will process it shortly. You will receive a shipping notification with your tracking number via email once your order has shipped.

If you have any questions about your order, please call us at 800-533-2210 or email us by responding to this email. Also, please let us know how we're doing by filling out our [30-second customer survey](#).

Sincerely,

Atlantic British Ltd. Customer Service

Your Order Number:

RP-5080938

Shipping Information:



Items Ordered:

Description	Quantity	Unit Price	Amount
Item #: 9284 Performance Shock Kit From Bilstein, Front & Rear Shocks For Range Rover Classic 1993-1995	1	\$539.95	\$539.95

Subtotal: \$539.95

Shipping: \$17.97

Tax: \$40.45

Total: \$598.37

Follow Us:



Manage email Preferences: Too many emails? [Click Here](#) to choose how often you receive emails.

Unsubscribe: [Click Here](#) to unsubscribe from our promotional email list.

To speak with a Customer Service Representative, call us toll-free at 800-533-2210.

[Click Here](#) to read our privacy statement.

Atlantic British Ltd. is an independent supplier and manufacturer of replacement parts and accessories for Land Rover vehicles. We have no affiliation, real or implied, with Land Rover UK Ltd. or Land Rover North America. Any use of Range Rover, Land Rover or other trademarks used in this message or on our website is intended for reference only. Parts and accessories provided by Atlantic British Ltd. are genuine Land Rover parts only if indicated by suffix 'G' in the part number on the part itself and/or the packaging associated therewith.

Atlantic British Ltd. | 6 Enterprise Ave | Clifton Park, NY 12065 | United States | 800-533-2210

© Atlantic British Ltd. All rights reserved.

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE
 SALES
 PARTS
 ACCESSORIES

Invoice No.
35914

Ref: TAG# 397

Order Date 03/17/21 12:36 pm
 Completed: 05/26/21 04:32 pm

1
 LOS GATOS CA 95032
 Mobile:

95 LAND ROVER RANGE ROVER B1
 157498 Mi. Last in 11/23/2020
 Lic: 3LBM614/CA V8Cyl 4.2
 Vin: SALHF1347SA654716 01/95
 Eq: AT AC PS FI 4W

Quotes
 1 03/01/21 01:09pm 2998.93
 in person.

Job01 Transfer Case

Labor: \$1,080.00

Customer request to have transfer case replaced. Removed and replace transfer case assembly with new part as per customer request with s/o part from Rovers North and retest High and Low gears. All ok at this time.

ROVNO	transfer case-S	1.0 @ 1499.95 = \$	1499.95
2420	COMPONENT CLEANER-N	1.0 @ 6.50 = \$	6.50
SHIPPING	SHIPPING-S	1.0 @ 400.00 = \$	400.00
TYC100070	CLIP-S	1.0 @ 25.32 = \$	25.32
			1931.77

Job02 Air Suspension

Labor: \$540.00

Customer states air suspension will not raise. Check history, check and advise. Upon inspection tech found that the EAS compressor is weak and valve block is leaking and not holding air. During further testing tech found that all 4 air springs are worn and cracking and bags are popping out of place. Recc replace compressor, valve block, all 4 air springs, exhaust silencer and drier and retest.

ANR4353	compressor EAS-N	1.0 @ 459.95 = \$	459.95	459.95
---------	------------------	-------------------	--------	--------

Job03 Valve Block

Labor: \$720.00

Replaced leaking valve block with good used part, dryer and muffler with new parts and retest. All ok at this time

RRS66626	MUFFLER 1650-S	1.0 @ 73.80 = \$	73.80
ANR3757	valve block -used-N	1.0 @ 750.00 = \$	750.00
NTC9812	dryer-N	1.0 @ 315.50 = \$	315.50
			1139.30

Job04 Air Springs

Labor: \$720.00

Replace front and rear air spring assemblies with new parts as per customer request and performed static test on system overnight. All ok at this time

ATBRIKI	FRONT AIR SPRING-S	2.0 @ 325.06 = \$	650.12
ATBRITRE	REAR AIR SPRING-S	2.0 @ 325.06 = \$	650.12
			1300.24

----->----->----->---Continued on the next page--->----->----->----->

L PARTS ARE NEW UNLESS SPECIFIED OTHERWISE



CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X CUSTOMER ACKNOWLEDGMENT

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE BRITISH EUROPEAN INC.

Land Rover ■ Jaguar service center

2921 Winchester Blvd. ■ Campbell, CA 95008

(408) 374-0131 ■ (408) 374-2143 fax

www.ebemotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.

35914

Page 2

Ref: TAG# 397

Order Date 03/17/21 12:36 pm

Completed: 05/26/21 04:32 pm

Job05 Drive Belt

Labor: \$342.00

Upon inspection tech found that there is a loud noise from the engine area. During testing tech found that drive belt tensioner is worn out and bearing is noisy and belt is worn. Removed and replaced drive belt and drive belt tensioner as per customer request and retest. All ok at this time

ERR3440	tensioner-N	1.0 @	205.20 = \$	205.20	
7PK2245	drive belt-S	1.0 @	45.20 = \$	45.20	250.40

Recommendations: multiple oil leaks, oil cooler and trans cooler hoses leak, motor mounts cracked/worn, transmission mounts cracked/worn,

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	3402.00
Parts	5081.66
Haz Waste	0.00
Subtotal	8483.66
Tax	470.05
Total	\$8953.71
Payments	0.00
Bal Due	8953.71

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE



CREDIT CARDS ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price. X

CUSTOMER ACKNOWLEDGMENT

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
 SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE



INVOICE

Date: 12/19/2021 **Order#:** 11072

Bill To: (Customer ID#7100)

R
Los Gatos, CA 95032
United States

Ship To:

Ric
Los Gatos, CA 95032
United States
9 27

Payment Method:

PayPal

Shipping Method:

Free Standard Shipping

Code	Description	Qty	Price	Total
YWB10027L	Range Rover Discovery Yellow Relay GENUINE	1	\$20.00	\$20.00

Subtotal: \$20.00
Tax: \$0.00
Shipping & Handling: \$0.00
Grand Total: \$20.00

Thank you for your order

1 message

Crutchfield <noreply@crutchfield.com>

To: [REDACTED]

Sun, Jul 31, 2022 at 2:30 PM



We're here to help
1.800.319.2606



Thanks for your order, [REDACTED]!

We'd like you to know:

- When your order ships, we will email your tracking information.
- Your order number is 50851381.

[View order status](#)

Questions? Call us at [1-800-319-2606](tel:1-800-319-2606).

Order #50851381

Billing address

[REDACTED]
[REDACTED]
[REDACTED]

Shipping address

[REDACTED]
[REDACTED]
[REDACTED]

ITEM	QTY	PRICE
------	-----	-------



Pioneer CD-MC20
Microphone

1

\$20.00



Pioneer AVH-3500NEX

1


\$700.00

TuneIn 3
months
Premium 5/1 -
10/30/2022
offer code

TuneIn 3 months Premium 5/1
- 10/30/2022 offer code

1

\$0.00



Metra 70-9400 Receiver
Wiring Harness

1

\$0.00

Subtotal: \$720.00

Sales tax
(CA): \$66.64

Shipping: Free

Order total \$786.64

✓ **Paid by Mastercard: \$786.64**

Thanks from all of us here in Virginia!

See your Goodyear.com order 0643029174 and installation details.

1 message

Your Goodyear Team <order@buy.goodyear.com>
Reply-To: "order@buy.goodyear.com" <order@buy.goodyear.com>
To: [REDACTED]

Tue, Aug 9, 2022 at 8:03 PM



Roll by Goodyear
Mobile Tire Installation comes to you.

You're good to go.

Thank you, your order has been placed.

Goodyear.com Order Number: 0643029174

Richard, we appreciate your decision to buy online from Goodyear. We're confident that you'll be happy with your new Goodyear Wrangler® All-Terrain Adventure With Kevlar® tires.

Your Roll by Goodyear Mobile Tire installation appointment has been confirmed. In the unlikely event of a scheduling conflict, we will contact you directly as soon as possible.

Zero Contact Mobile Tire Installation

1. Prepare for your appointment by writing down your odometer (mileage) reading and disabling any vehicle alarms.
2. Meet the technician at the time of your appointment, maintaining an appropriate social distance, to verify your information and vehicle details.
3. When work is finished, you'll be asked to verify your Tire Pressure Monitoring System (TPMS) light is off.
4. We'll verify that your Photo ID and credit card match and will ask you to sign your invoice.

Roll Mobile Tire Installation Requirements

To ensure a smooth installation experience, please follow these guidelines:

- Vehicle must be parked in a safe place off the roadway to perform services
- You must **show photo identification** that matches your order invoice
- **You must have permission** for Roll by Goodyear to service your vehicle where parked
- We'll need at least **5 feet of space** on all sides of your vehicle
- If parked in a covered location, we'll need **10 feet of vertical clearance** for our Roll by Goodyear van
- If your wheels have wheel locks, you must provide the wheel lock key

Need help?

For questions about your order or installation appointment, call us anytime at [800-667-8138](tel:800-667-8138) from:

Monday – Friday: 9:00 AM – 6:00 PM EST

Saturday: 9:00 AM – 6:00 PM EST (Post Purchase Support Only)

Sunday: CLOSED

- [Buying Tires Online FAQs](#)

Your purchase was billed to:



INSTALLATION INFORMATION

Your mobile installation appointment has been confirmed. In the unlikely event of a scheduling conflict, we will contact you directly as soon as possible.

Your new tires will be installed at:

Requested Installation Time:



Saturday



August 13, 2022
8:00 AM - 10:00 AM

Mobile Tire Installation, San Jose
844-824-4768

What to Expect During Your Mobile Installation



ROLL BY GOODYEAR

YOUR TIRES



Goodyear Wrangler[®] All-Terrain Adventure With Kevlar[®]

Your Selected Vehicle: No Vehicle Entered

Your Selected Tire Size: LT225/75R16/E

Product Code: 748748572

Tires **\$912.00**

Qty: 4

Discount *-\$182.40*

Installation **\$75.80**

Parts

Labor

Taxes & Fees **\$89.82**

Tire Disposal Fee

Sales Tax

Waste Tax

Total: **\$895.22**

Tire rebate on a set of 4† -\$75.00

Your 20% Off Discount code has been applied!

Claim your **\$75** Goodyear MasterCard® Prepaid Card.

HERE'S HOW:

BY MAIL

Download [Mail-In Rebate Form](#)

You will be asked to include this confirmation email. Please print this page.

OR

ONLINE

Go to [Goodyear Tire Rebate Center](#)

What you need

- Your offer number: 220015
- Your rebate form code: 22TSN2_RebateForm_GYCC_20905 220015_KIT_TSN2
- In Step 2, please do not fill the zip code in the first box. Instead select "Purchased Online" from the second box.
- Your order number: 0643029174 (same as order number from top of your confirmation email)

You will be asked to upload this confirmation email. Please save this page as a JPG or PDF.



Payment

MASTERCARD ending in _____

Expiration: 07/2025

[Return Policy](#)

Purchase Date:

08/09/2022

[Privacy Policy](#)

[Tire Care Toolkit](#)

[Tire Warranty Info](#)

[Register Tires](#)

[Returns Policy](#)

© 2021 The Goodyear Tire & Rubber Company
200 Innovation Way, Akron, OH 44316

Goodyear Credit Card transactions: the terms of the offer and applicable law governs this transaction including increasing APRs and fees.

*** TERMS AND CONDITIONS OF SALE ON WWW.GODYEAR.COM**

THESE TERMS OF SALE (THE "TERMS AND CONDITIONS OF SALE") GOVERN YOUR PURCHASE OF ANY PRODUCT OR SERVICE OFFERED BY THE GOODYEAR TIRE & RUBBER COMPANY ("Goodyear") ON THE WWW.GODYEAR.COM WEBSITE (THE "Website"). PLEASE READ THESE TERMS AND CONDITIONS OF SALE CAREFULLY. THEY CONTAIN VERY IMPORTANT INFORMATION ABOUT YOUR RIGHTS AND OBLIGATIONS, AS WELL AS LIMITATIONS AND EXCLUSIONS THAT MAY APPLY TO YOU. THEY ALSO CONTAIN AN ARBITRATION CLAUSE AND CLASS ACTION WAIVER. BY CLICKING ON THE "I AGREE BUTTON" OR BY PLACING AN ORDER, YOU ("YOU" AND/OR "CUSTOMER" HEREIN) ACKNOWLEDGE THAT YOU HAVE READ, ACCEPTED, AND AGREED TO BE BOUND BY THESE TERMS AND CONDITIONS OF SALE, WITHOUT LIMITATION OR QUALIFICATIONS. THESE TERMS AND CONDITIONS OF SALE ARE SUBJECT TO MODIFICATION, SO PLEASE READ THESE TERMS AND CONDITIONS OF SALE EACH TIME YOU MAKE A PURCHASE.

1. Products. Goodyear is authorized to sell the products and/or services offered for sale on the Website. Goodyear may discontinue any product and/or service at any time without notice. The prices advertised on the Website for the products and services do not include shipping and handling or sales taxes, if applicable, which will be added to your total invoice price.

DR INVOICE
0000001002
08/14/2022

Goodyear
Auto Service Centers 1287
995 Blossom Hill Rd
San Jose, CA 95123
510-277-5012
Federal Tax Id 340253240

Operator: Camila Janali Cipr
BAR/MVR:ARD180691

Bill To:
GOODYEAR ECOMMERCE
FRIENDS AND
Customer No.
000237153

Ship To:
[REDACTED]
Customer No.
1287000364

Vehicle Info:
Year: 1995
Make: LAND ROVER
Model: RANGE ROVER
Color:
License/State: 3Lbm614/CA

Odom I/O: 158398/158398
Vehicle In: 08/13 10:36 AM
Vehicle Out: 08/14 06:07 PM

DRIVER DETAILS

Name: [REDACTED]
Address: [REDACTED]
Phone: [REDACTED]

PRODUCT	DESCRIPTION	QTY	PART	LABOR	TOTAL
046605000	GYCOM TIRE DISPOSAL FEE	4.00	0.00	3.00	12.00
044357000	GYCOM INSTALLATION PACKAGE TIER 1 PR	4.00	5.00	13.95	75.80
VS1R	STD RUBBER VALVE STEM	4.00			
748748572	LT225/75R16 115R E WRL AT ADVENTURE BSL	4.00			
	(1, 2, 3, 4) PL1LC41V1922				

Signature [REDACTED]

DELIVERY RECEIPT DO NOT PAY

Salesperson	Technician	Services
Shakeh Malekian	Shakeh Malekian	044357000, 046605000, 748748572

REVISED ESTIMATE AUTHORIZATIONS

Auth By: Ronny J Ventura
Auth By: Ronny J Ventura
Cont: [REDACTED] **Approved By:**
Cont: [REDACTED] **Date/Time:** 08/13 10:36 **Prev Est:** 87.80 **Approved By:**

NA REQUIREMENTS

PO/SC/COUPON/ID # 0643029174
LIC # & STATE 3Lbm614 CA
ODOMETER/HUBDOMETER REA 158398
VEHICLE TYPE 1995 LAND ROVER RANGE ROVER

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.
39089

Page 1

Order Date 01/09/23 08:07 am
 Completed: 01/12/23 01:21 pm

E
 1
 LOS GATOS CA 95032
 Mobile:

95 LAND ROVER RANGE ROVER B1
 159349 Mi. Last in 5/20/2022
 Lic: 3LBM614/CA V8Cyl 4.2
 Vin: SALHF1347SA654716 01/95
 Eq: AT AC PS FI 4W

Quotes
 1 01/09/23 08:11am 273.21
 in person.

Job01 RR 1995 Oil Service

Labor: \$150.00

Perform service as per checklist
 Replace oil and filter
 Rotate Tires
 Set tires to recommended pressure

ERR3340	oil filter-N	1.0 @	22.60 =\$	22.60
213961L	Drain plug washer-N	1.0 @	3.10 =\$	3.10
10W/30	AC DEL.-N	7.0 @	11.50 =\$	80.50 106.20

Job02 Surcharge

Sublet: \$120.00

Recommendations: multiple oil leaks, oil cooler and trans cooler hoses leak, motor mounts cracked/worn, transmission mounts cracked/worn,

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	150.00
Parts	106.20
Haz Waste	7.05
Sublet	120.00
Subtotal	383.25
Tax	9.96
Total	\$393.21
Payments	0.00
Bal Due	393.21

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X
 CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
 SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN
SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

■
SALES

■
PARTS

■
ACCESSORIES

LUBE AND OIL SERVICE

- REPLACE ENGINE OIL
- REPLACE ENGINE OIL FILTER
- REPLACE ENGINE OIL PLUG SEALING WASHER
- CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED
- CHECK AND REPORT ON ENGINE OIL LEAKS
- CHECK AND REPORT ON TRANSMISSION OIL LEAKS
- CHECK AND REPORT ON CONDITION OF COOLANT
- CHECK AND REPORT ON COOLING FAN OPERATION
- CHECK AND REPORT ON ALL ENGINE
- INSPECT AIR FILTER ELEMENT
- TEST BATTERY
- INSPECT CLUTCH OPERATION (IF APPLICABLE)
- TEST AND ADVISE HEATER AND AIR CONDITIONING OPERATION
- TEST DISTRIBUTION VACUUM ADVANCE & REPORT (IF APPLICABLE)
- CHECK LIGHTS AND HORN OPERATION
- INSPECT WIPER AND WIPER BLADE OPERATION & CONDITION
- LUBRICATE ALL DOOR HINGES, HOOD/TRUNK LATCH MECHANISMS
- ROTATE TIRES, CHECK & ADVISE ON TIRE WEAR (DO NOT ROTATE IF DIFFERENT SIZES)
- CHECK WHEEL LUG TORQUE & ADJUST TO SPECS
- CHECK PRESSURE AND ADJUST TO SPECS ON ALL TIRES
- INSPECT EMERGENCY BRAKE OPERATION
- INSPECT SUSPENSION BOLTS/NUTS
- BRAKES AND ROTORS FRONT% 11mm REAR% 9mm
- INSPECT STEERING AND SUSPENSION & LUBE AS NEEDED
- INSPECT EXHAUSE SYSTEM & CATALYTIC CONVERTER
- CHECK TRANSMISSION FLUID LEVEL INSPECT
- CHECK DIFFERENTIAL FLUID AND CONDITION
- RESET OIL SERVICE LIGHT (IF APPLICABLE)
- INSTALL SERVICE REMINDER STICKER ON WINDSHIELD
- TEST DRIVE CAR AND REPORT

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

esp-global.com

Test Date/Time: 01/11/2023@16:32:58

Model Year: 1995	Make: LAND ROVER	Model: RANGE ROVER COUNTY LWB
License: 3LBM614	State: CA	VIN: SALHF1347SA654716
Engine Size: 4.20 L	Type: Truck	Transmission: Automatic
GVWR: 6019	Test Weight: N/A	Cylinders: 8
Odometer: 159,315	Certification: California	VLT Record #: 26573
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: TC121141

DMV ID Number: 1735C474T206

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB08	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		%O2			HC (PPM)		CO (%)		MEAS	Results
		MEAS	AVE	MAX	AVE	MEAS	MAX	AVE	MEAS	Results		
Idle	698	14.9	0.2	100	26	9	1.00	0.00	0.00	Pass		
2500 RPM	2364	14.8	0.4	180	11	3	1.10	0.10	0.00	Pass		

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

ACCURATE SMOG CHECK
238 Curtner Ave Campbell CA 95006
4083891876
Station Number: TM231385

Technician Name/Number: RUMBLER, PAUL/EO031280
Repair Tech Name/Number:
Software Version/EIS Number: 190 EP728430

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date: 1-11-23

Technician's Signature: _____

Billing address

[Redacted]
[Redacted]
[Redacted]
US

Delivery address

[Redacted]
[Redacted]
[Redacted]
US

Sold By

Globale UK Limited
154 Clerkenwell Road
London, EC1R 5AB
United Kingdom
Tax ID # 177 9006 80

Order Information

Order # GE3567326321GB
Order date 26 February 2023
Order placed by [Redacted]
Shipping Method Express Courier (Air)
Payment Details Paypal

Ordered Items

Description	Qty	Unit price	Item subtotal
YUE10005L.L8-SWITCH - GLOVE COMPARTMENT LIG	2	\$ 15.73	\$ 31.46

Items Total \$ 31.46
Shipping & Handling \$ 28.39
Total \$ 59.85

Your RoverParts.com Order Has Been Placed - Order No. RP-5187817

1 message

Atlantic British <atlanticbritish@enews.roverparts.com>

Tue, May 9, 2023 at 11:44 AM

Reply-To: inquiry@atlanticbritish.com

To: [REDACTED]

If you cannot see the images below, select "Show Images" in your browser or [Click Here](#) to view this message online.



 **800.533.2210**
Monday - Friday 8am - 6pm Eastern

Dear Richard Baker,

Thank you for shopping with Atlantic British Ltd.! We have received your order and will process it shortly. You will receive a shipping notification with your tracking number via email once your order has shipped.

Order Processing & Shipping:

- We process and ship orders Mon-Fri. We do not ship on weekends or holidays.
- **Pandemic Slowdown:** We will ship your order as quickly as possible, but cannot ship all orders the same day they are received, as we face pandemic challenges like many companies. We ask for your patience and we appreciate it. Shipping carriers have suspended delivery service guarantees as well - see bottom of this message for more details...
- You will be notified via email when your order ships with package tracking number(s) provided.
- [Contact Us](#) or call us with shipping questions [Click Here](#) for more shipping information.

If you have any questions about your order, please call us at **800-533-2210** or email us by responding to this email. Also, please let us know how we're doing by filling out our [30-second customer survey](#).

Sincerely,

Your Order Number:

RP-5187817

Shipping Information:



Items Ordered:

Description	Quantity	Unit Price	Amount
Item #: ETC7150G Genuine Cruise Control Actuator ETC7150 For Land Rover Discovery I, Discovery Series II, Range Rover P38, And Range Rover Classic	1	\$126.95	\$126.95
Item #: NTC6086 Rear Bump Stop NTC6086 For Range Rover Classic, 1993 - 1995, Air Suspension	2	\$19.95	\$39.90

Subtotal: \$166.85

Shipping: \$15.09

Tax: \$13.19

Total: \$195.13

Shipping Carrier Delivery Information

You will receive a separate email with your tracking number once your order has been processed. All prior quoted shipment arrival dates are ESTIMATES only and your package could be delayed beyond that estimate. Please check the tracking status regularly for your package progress.



EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebomotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.
40265

Page 1

Order Date 08/07/23 08:24 am
 Completed: 10/13/23 11:59 am

LOS GATOS CA 95032
 Mobile:

95 LAND ROVER RANGE ROVER BI
 161474 Mi. Last in 1/9/2023
 Lic: 3LBM614/CA V8Cyl 4.2
 Vin: SALHF1347SA654716 01/95
 Eq: AT AC PS FI 4W

Quotes
 1 08/07/23 08:28am 17067.99
 in person.

Job01 Engine Assembly

Labor: \$6,300.00

Customer request to have engine replaced. Remove engine assembly and repalce with new unit from Atlantic British. Replaced water pump, spark plugs, ignition wires, oil pan gasket, hoses, air filter, fuel filter, drive belt, engine mounts, transmission mounts, and thermostat as per customer request and road test vehicle. All ok at this time. Warranty on engine assembly is 12 months/12,000 miles. NOTE: recc customer returns in 1,000 miles for oil service and retest of engine assembly.

ERR7280	gasket timing cover-N	1.0 @	35.50 = \$	35.50
LRN2279	COOLANT-N	4.0 @	47.95 = \$	191.80
10W/30	AC DEL.-N	6.0 @	11.50 = \$	69.00
ERR6621	intake gasket upper-N	1.0 @	55.00 = \$	55.00
STC4378	WATER PUMP-N	1.0 @	320.20 = \$	320.20
LVF100400	oil pan gasket-N	1.0 @	52.56 = \$	52.56
ERR4528	hose-S	1.0 @	19.95 = \$	19.95
PEH101530	hose-N	1.0 @	17.34 = \$	17.34
ETC4765	THERMOSTAT-N	1.0 @	21.55 = \$	21.55
SHIPPING	SHIPPING-S	1.0 @	500.00 = \$	500.00
ETC4524	Flange gaskets-N	2.0 @	14.95 = \$	29.90
BTR8726	hose heater-N	1.0 @	65.20 = \$	65.20
9257DLR1K	4.6 LONG BLOCK-S	1.0 @	7795.95 = \$	7795.95
ERR3799	SPARK PLUGS-N	8.0 @	9.95 = \$	79.60
ESR1445	Air filter-N	1.0 @	17.17 = \$	17.17
C2C35417	fuel filter-N	1.0 @	42.97 = \$	42.97
368	wire set-N	1.0 @	105.24 = \$	105.24
XXPPP	paint-S	2.0 @	19.95 = \$	39.90
2420	COMPONENT CLEANER-N	1.0 @	6.50 = \$	6.50
25-070885	belt-S	1.0 @	88.04 = \$	88.04
951 106 245 03	Upper rad hose-N	1.0 @	86.10 = \$	86.10
ERR4686	plug radiator-N	1.0 @	6.95 = \$	6.95
STC434	mounts motor-N	2.0 @	65.30 = \$	130.60
ANR2621	MOUYNT-S	2.0 @	49.20 = \$	98.40

9875.42

Job02 Cooler Lines

Labor: \$345.00

----->----->----->-----Continued on the next page----->----->----->----->

LL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.
 CUST. X
 SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.

40265

Page 2

Order Date 08/07/23 08:24 am

Completed: 10/13/23 11:59 am

Job02 Cooler Lines

Replaced transmission cooler hoses, power steering hoses, and engine oil cooler lines as per customer request

SEAC.	TRANSMI COOL. LI-S	1.0 @	165.00 =	\$	165.00
SEAC	TRANS. COOL. LIN-S	1.0 @	165.00 =	\$	165.00
SEAC.	ENGINE COOLER.-S	1.0 @	150.20 =	\$	150.20
SAEAC.	ENGINE LINE-S	1.0 @	165.00 =	\$	165.00
40795700	o rings-S	12.0 @	5.20 =	\$	62.40
NTC9989	Hose-N	1.0 @	49.57 =	\$	49.57
SEACE.	TRANS. COOLER LINE-S	1.0 @	175.95 =	\$	175.95
					933.12

Job03 Engine Clean

Sublet: \$120.00

Job04 Hood Liner

Sublet: \$350.00

Removed and replaced hood liner with new part as per customer request. All ok at this time

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	6645.00
Parts	10808.54
Sublet	470.00
Haz Waste	12.00
fuel	50.00
Subtotal	17985.54
Tax	1013.30
Total	\$18998.84
Payments	0.00
Bal Due	18998.84

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD



CREDIT CARDS
ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE



Fwd: Order #2504 confirmed

1 message

To:

Tue, Dec 26, 2023 at 12:38 PM

Begin forwarded message:

From: Congleton Service <info@congletonservice.com>

Date: November 24, 2023 at 4:31:41 PM PST

Subject: Order #2504 confirmed



Thank you for your purchase!

Hi , we're getting your order ready to be shipped. We will notify you when it has been sent.

[View your order](#) or [Visit our store](#)

Order summary



1995 Range Rover Classic Steering Wheel x 1

SAVE 25% ON ALL ORDERS >\$300 (-\$150.00)

\$450.00

Subtotal **\$450.00**

Shipping **\$12.76**

Total \$462.76 USD

You saved \$150.00

Customer information

Shipping address

[Redacted shipping address]

Billing address

[Redacted billing address]

Shipping method

Ground Advantage

Payment method



Payment method

info@conletonservice.com

**EXCLUSIVE
BRITISH
EUROPEAN**

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE
■
SALES
■
PARTS
■
ACCESSORIES

Invoice No.
41851

Page 2

Order Date 05/13/24 08:05 am
Completed: 05/16/24 04:34 pm

Payments to Exclusive British European

Cost Summary

Status: Completed Work Order

Payments:

Labor	447.50
Parts	163.05
Haz Waste	7.05
Shipping	12.98
Subtotal	630.58
Tax	15.29
Total	\$645.87
Payments	0.00
Bal Due	645.87

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE



**CREDIT CARDS
ACCEPTED**



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price.

X

CUSTOMER ACKNOWLEDGMENT

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. X
SIG.

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

■
SALES

■
PARTS

■
ACCESSORIES

LUBE AND OIL SERVICE

- REPLACE ENGINE OIL
- REPLACE ENGINE OIL FILTER
- REPLACE ENGINE OIL PLUG SEALING WASHER
- CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED
- CHECK AND REPORT ON ENGINE OIL LEAKS
- CHECK AND REPORT ON TRANSMISSION OIL LEAKS
- CHECK AND REPORT ON CONDITION OF COOLANT
- CHECK AND REPORT ON COOLING FAN OPERATION
- CHECK AND REPORT ON ALL ENGINE
- INSPECT AIR FILTER ELEMENT
- TEST BATTERY
- INSPECT CLUTCH OPERATION (IF APPLICABLE)
- TEST AND ADVISE HEATER AND AIR CONDITIONING OPERATION
- TEST DISTRIBUTION VACUUM ADVANCE & REPORT (IF APPLICABLE)
- CHECK LIGHTS AND HORN OPERATION
- INSPECT WIPER AND WIPER BLADE OPERATION & CONDITION
- LUBRICATE ALL DOOR HINGES, HOOD/TRUNK LATCH MECHANISMS
- ROTATE TIRES, CHECK & ADVISE ON TIRE WEAR (DO NOT ROTATE IF DIFFERENT SIZES)
- CHECK WHEEL LUG TORQUE & ADJUST TO SPECS
- CHECK PRESSURE AND ADJUST TO SPECS ON ALL TIRES
- INSPECT EMERGENCY BRAKE OPERATION
- INSPECT SUSPENSION BOLTS/NUTS
- BRAKES AND ROTORS FRONT% 1mm REAR% 2mm
- INSPECT STEERING AND SUSPENSION & LUBE AS NEEDED
- INSPECT EXHAUSE SYSTEM & CATALYTIC CONVERTER
- CHECK TRANSMISSION FLUID LEVEL INSPECT
- CHECK DIFFERENTIAL FLUID AND CONDITION
- RESET OIL SERVICE LIGHT (IF APPLICABLE)
- INSTALL SERVICE REMINDER STICKER ON WINDSHIELD
- TEST DRIVE CAR AND REPORT

Customer Copy

RC Refinishing

408-298-1989

1617 Pomona Ave, San Jose CA

Sales@RcRefinishing.com

Picked Up / Paid

5/2/2024

Customer / Company Name

Job Status

Date

Contact: Phone / Email / Address

Bruch guard, tail light guard - Black \$450
mailbox - white \$75- \$150

Bruch guard, tail light guard - Black
\$450 6 5.5

mailbox - white \$75- \$150

\$600 total

\$550 cash

Item(s) Description / Instructions

Pricing \$


Colors

Warning: This product may contain chemicals known to the state of California to cause cancer, birth defects and other reproductive harm. For more information visit www.p65warnings.ca.gov



Order #2707 confirmed

1 message

Congleton Service <store+8479178848@t.shopifyemail.com>
Reply-To: Congleton Service <info@congletonservice.com>
To: 

Mon, May 13, 2024 at 7:43 AM

**Thank you for your purchase!**

Hi Richard, we're getting your order ready to be shipped. We will notify you when it has been sent.

[View your order](#) or [Visit our store](#)

Order summary

Range Rover Classic Hardware Kit for Rear Lamp
Guards x 1 **\$50.99**



Range Rover Classic Hardware Kit for Rear Lamps x 1 **\$50.70**

Discount  25OFF	-\$25.43
Subtotal	\$76.26
Shipping	\$9.21

Total

\$85.47 USD

You saved \$25.43

Customer information

Shipping address

[Redacted shipping address]

Billing address

[Redacted billing address]

Shipping method

Ground Advantage

Payment method



Payment method

info@congletonservice.com



6 Enterprise Avenue
Clifton Park, New York 12065 USA

4109 Guardian Street
Simi Valley, California 93063 USA

INVOICE

Invoice Number
1652572

Customer Number
525038

Bill to:

1
LOS GATOS, CA 95032 US

Phone:

Ship to:

F
LOS GATOS, CA 95032

Range Rover • Discovery • LR3/LR4 • Freelander/LR2 • Defender • LR Series • MINI Cooper
All Returns Must Be Accompanied By Invoice. See Reverse For Return Information and Store Policies.

DATE	SHIP VIA	F.O.B.	TERMS			
05/28/24 07:55 PM	USPSGA	SIMI VALLEY, CA	PPWEB			
PHONE NUMBER	ORDER DATE	SALES PERSON	OUR ORDER NUMBER			
972/672-5727	05/28/2024	Chip French - Ext 233	1790391			
ORDERED	SHIPPED	BACK ORD.	ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
2	2	0	PRC4615	WASHER JET HEADLAMP RR CLASSIC	14.95	29.90

Shipping Charges	4.95
NonTaxable Subtotal	0.00
Taxable Subtotal	34.85
Tax (7.25%)	2.53
Total (USD)	37.38

Thank You!

PHONE: 800-533-2210 or 518-664-6169 **FAX: 518-664-6641**
RoverParts.com • MiniCarParts.net • ClearviewMirrorsUSA.com

CONGLETON SERVICE

Order #2733
May 30, 2024

SHIP TO

Los Gatos CA 95032
United States

BILL TO

17
Los Gatos CA 95032
United States

ITEMS

QUANTITY



Range Rover Classic Exterior Body Molding Kit
LWB

1 of 1

There are other items from your order not included in this shipment.

Thank you for shopping with us!

Congleton Service

354 Prim Rd, Colchester, VT, 05446, United States

info@congletonservice.com

shop.congletonservice.com

CONGLETON SERVICE WARRANTY

Congleton Service offers a one-year warranty on Exclusive Congleton Service Parts. These parts are manufactured by Congleton Service and are specifically stated on our web store. They are available for exchange only, and only if found faulty by the manufacturer. Parts found faulty must include proof of professional installation (e.g., a copy of a dated invoice for installation of the part).

In no event shall Congleton Service be liable for any incidental or consequential damages. This warranty shall not apply if:

- Damage occurred due to improper installation or use;
- Corrosion or damage occurred due to improper maintenance;
- Damage or structural failure occurs as a result of an accident or road conditions, including off-road use;
- The product or vehicle is used for commercial purposes, off-road use, or on or off-road racing.

Please notify us immediately if a potential warranty situation arises and we will advise on next steps. If part was damaged in transit, we must be alerted within 24 hrs of delivery so please open your package to inspect it immediately. A suspected faulty part must be returned to us together with the original invoice and proof of professional installation. A suspected faulty part must be returned and received by us before we can do a physical inspection. We do not provide reimbursements for Congleton Service Parts. Parts found defective by the manufacturer (Congleton Service) will be exchanged for a replacement of the same part only. For warranty claims please state vehicle chassis number, date fitted by a technician and mileage, date failed and mileage, and exact nature of fault. No claim will be validated if the failure is caused by misuse, neglect, overheating, incorrect installation or failure of a related component. Warranties are not transferable. Acceptance of Congleton Service Parts is deemed as acceptance of these terms.

The seller, Congleton Service, hereby expressly disclaims all warranties from manufacturers other than Congleton Service. Including any warranty of implied merchantability or fitness for a particular purpose. Congleton Service neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of said products.

If you have any questions, reply to this email or contact us at info@congletonservice.com

CONGLETON SERVICE

Order #2733
May 30, 2024

SHIP TO

1
Los Gatos CA 95032
United States

BILL TO

1
Los Gatos CA 95032
United States

ITEMS

QUANTITY



Congleton Rear Bumper Dust Seal - RRC / NAS Defender
CS-DSTSL

1 of 1

There are other items from your order not included in this shipment.

Thank you for shopping with us!

Congleton Service

354 Prim Rd, Colchester, VT, 05446, United States

info@congletonservice.com

shop.congletonservice.com

CONGLETON SERVICE WARRANTY

Congleton Service offers a one-year warranty on Exclusive Congleton Service Parts. These parts are manufactured by Congleton Service and are specifically stated on our web store. They are available for exchange only, and only if found faulty by the manufacturer. Parts found faulty must include proof of professional installation (e.g., a copy of a dated invoice for installation of the part).

In no event shall Congleton Service be liable for any incidental or consequential damages. This warranty shall not apply if:

- Damage occurred due to improper installation or use;
- Corrosion or damage occurred due to improper maintenance;
- Damage or structural failure occurs as a result of an accident or road conditions, including off-road use;
- The product or vehicle is used for commercial purposes, off-road use, or on or off-road racing.

Please notify us immediately if a potential warranty situation arises and we will advise on next steps. If part was damaged in transit, we must be alerted within 24 hrs of delivery so please open your package to inspect it immediately. A suspected faulty part must be returned to us together with the original invoice and proof of professional installation. A suspected faulty part must be returned and received by us before we can do a physical inspection. We do not provide reimbursements for Congleton Service Parts. Parts found defective by the manufacturer (Congleton Service) will be exchanged for a replacement of the same part only. For warranty claims please state vehicle chassis number, date fitted by a technician and mileage, date failed and mileage, and exact nature of fault. No claim will be validated if the failure is caused by misuse, neglect, overheating, incorrect installation or failure of a related component. Warranties are not transferable. Acceptance of Congleton Service Parts is deemed as acceptance of these terms.

The seller, Congleton Service, hereby expressly disclaims all warranties from manufacturers other than Congleton Service. Including any warranty of implied merchantability or fitness for a particular purpose. Congleton Service neither assumes nor authorizes any other person to assume for it any liability in connection with the sales of said products.

If you have any questions, reply to this email or contact us at info@congletonservice.com

Edit Order

Connect your site to activate WooCommerce Shipping & Tax

WooCommerce Shipping & Tax is almost ready to go! Once you connect your site to WordPress.com you'll have access to automated tax calculation and shipping label printing.

By clicking "Connect", you agree to our [Terms of Service](#) and have read our [Privacy Policy](#).

Connect

Order #79683 details

Payment via PayPal (4YG61790Y1467451V). Paid on June 13, 2024 @ 1:07 am. Customer IP: 73.63.188.161

General

Date created:

2024-06-13 @ 01:06

Status

Processing

Customer:

Guest

VIN #:

- Not specified -

Billing

R

17

Los Gatos, CA 95032

Email address:

.com



Phone:

5

Shipping

1

Los Gatos, CA 95032

Item	Cost	Qty	Total
 LAND ROVER FRONT / REAR MUDFLAPS x2 RANGE MXC5587 OEM SKU: MXC5587GEN	\$88.04	x 1	\$88.04
 Free shipping			\$0.00
Items: LAND ROVER FRONT / REAR MUDFLAPS x2 RANGE MXC5587 OEM x 1			
Items Subtotal:			\$88.04
Shipping:			\$0.00
Order Total:			\$88.04
Paid:			\$88.04
June 13, 2024 via PayPal			
PayPal Fee:			-\$3.47
PayPal Payout:			\$84.57

EXCLUSIVE
BRITISH
EUROPEAN

SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
 (408) 374-0131 ■ (408) 374-2143 fax
 www.ebemotors.com

SERVICE
 ■
 SALES
 ■
 PARTS
 ■
 ACCESSORIES

Invoice No.
42884

Page 1

Order Date 11/05/24 07:49 am
 Completed: 11/05/24 12:21 pm

1
 LOS GATOS CA 95032
 Mobile: 9

95 LAND ROVER RANGE ROVER B1
 ODO in:163577 out:
 Lic: 3LBM614/CA V8Cyl 4.2
 Vin: SALHF1347SA654716 01/95
 Eq: AT AC PS FI 4W

Last in 5/13/2024

Quotes
 1 11/05/24 07:57am 424.31
 in person.

Job01 RR 1995 Oil Service Labor: \$190.00

Perform service as per checklist
 Replace oil and filter
 Rotate Tires
 Adjust tires to recommended pressure ft 36psi, rear 44psi
 Reset maint reminder

VYX000040	drain plug gasket-N	1.0 @	1.50 =\$	1.50
2943	Washer Fluid-N	1.0 @	6.50 =\$	6.50
ERR3340	oil filter-N	1.0 @	25.95 =\$	25.95
10W/30	AC DEL.-N	8.0 @	12.50 =\$	100.00
				133.95

Job02 Surcharge Sublet: \$125.00

Payments to Exclusive British European Cost Summary

Status: Completed Work Order	Labor	190.00
Payments:	Parts	133.95
	Sublet	125.00
	Haz Waste	7.80
	Subtotal	456.75
	Tax	12.56
	Total	\$469.31
	Payments	0.00
	Bal Due	469.31

Thank you for choosing Exclusive British European

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE



CREDIT CARDS
 ACCEPTED



WE RESERVE THE RIGHT TO REFUSE ANY PERSONAL CHECKS

I acknowledge notice and oral approval of an increase in the original estimated price. X

CUSTOMER ACKNOWLEDGMENT

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this side and the reverse of this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains within the Repair Garage.

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

READ IMPORTANT INFORMATION ON REVERSE SIDE

EXCLUSIVE
BRITISH
EUROPEAN
SPECIALIZING IN LAND ROVER & JAGUAR

2921 Winchester Blvd. ■ Campbell, CA 95008
(408) 374-0131 ■ (408) 374-2143 fax
www.ebemotors.com

SERVICE

■
SALES


■
PARTS

■
ACCESSORIES

LUBE AND OIL SERVICE

REPLACE ENGINE OIL
REPLACE ENGINE OIL FILTER
REPLACE ENGINE OIL PLUG SEALING WASHER
CHECK ALL FLUID LEVELS AND TOP OFF AS NEEDED
CHECK AND REPORT ON ENGINE OIL LEAKS
CHECK AND REPORT ON TRANSMISSION OIL LEAKS
CHECK AND REPORT ON CONDITION OF COOLANT
CHECK AND REPORT ON COOLING FAN OPERATION
CHECK AND REPORT ON ALL ENGINE
INSPECT AIR FILTER ELEMENT
TEST BATTERY
INSPECT CLUTCH OPERATION (IF APPLICABLE)
TEST AND ADVISE HEATER AND AIR CONDITIONING OPERATION
TEST DISTRIBUTION VACUUM ADVANCE & REPORT (IF APPLICABLE)
CHECK LIGHTS AND HORN OPERATION
INSPECT WIPER AND WIPER BLADE OPERATION & CONDITION
LUBRICATE ALL DOOR HINGES, HOOD/TRUNK LATCH MECHANISMS
ROTATE TIRES, CHECK & ADVISE ON TIRE WEAR (DO NOT ROTATE IF DIFFERENT SIZES)
CHECK WHEEL LUG TORQUE & ADJUST TO SPECS
CHECK PRESSURE AND ADJUST TO SPECS ON ALL TIRES
INSPECT EMERGENCY BRAKE OPERATION
INSPECT SUSPENSION BOLTS/NUTS
BRAKES AND ROTORS FRONT% 10mm REAR% 8mm
INSPECT STEERING AND SUSPENSION & LUBE AS NEEDED
INSPECT EXHAUSE SYSTEM & CATALYTIC CONVERTER
CHECK TRANSMISSION FLUID LEVEL INSPECT
CHECK DIFFERENTIAL FLUID AND CONDITION
RESET OIL SERVICE LIGHT (IF APPLICABLE)
INSTALL SERVICE REMINDER STICKER ON WINDSHIELD
TEST DRIVE CAR AND REPORT

Smog Check Vehicle Inspection Report (VIR)



www.esp-global.com

Vehicle Information



www.autorepair.ca.gov

Test Date/Time: 11/05/2024@10:55:12

Model Year: 1995	Make: LAND ROVER	Model: RANGE ROVER COUNTY LWB
License: 3LBM614	State: CA	VIN: SALHF1347SA654716
Engine Size: 4.20 L	Type: Truck	Transmission: Automatic
GVWR: 6019	Test Weight: N/A	Cylinders: 8
Odometer: 163,580	Certification: California	VLT Record #: 26573
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: UE725982

DMV ID Number: 1339E476U606

47

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>	<u>Result</u>	<u>ECS</u>
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB04	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

Test	RPM	%CO2		%O2			HC (PPM)			CO (%)		Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MEAS		
Idle	782	15.3	0.1	100	26	16	1.00	0.00	0.00		Pass	
2500 RPM	2392	15.3	0.2	180	11	9	1.10	0.10	0.01		Pass	

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

ACCURATE SMOG CHECK STAR CERTIFIED
238 Curtner Ave Campbell CA 95008
4083691676
Station Number: TM231385

Technician Name/Number: RUMPLER, PAUL/EO031280
Repair Tech Name/Number:
Software Version/EIS Number: 2402 / EP728430

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date 11-5-24

Technician's Signature